

BBS TRUCK PAINT AND BODY

2425 TRI-STATE RD
 TEXARKANA, TX, 75501
 Tel: 903-831-5049 Fax: 903-832-3729
 BBSTRUCK@YAHOO.COM
 Tax ID: 75-2816216

Vehicle Inspection

Inspected by:

Appraised for:

Accident Date:

Date of Loss:

Date: 9/17/2012

Estimate#: 330

Arrival Date:

Type of Loss:

Policy Number:

Claim Number:

Year	Make	Model	Color	Trim	License	Serial#/VIN#
2008	PETERBILT	388/389	RED/SILVER			1XPXD49X38D748 299
Wheelbase		Unit Number	Hubometer	Engine Hours		Odometer
						411000

Engine

Make	Model	Horsepower	Pur.Date/Amount	
CUMMINS	I S X	500		<input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel

Transmission

Make	Model	Speeds
FULLER	RTLO18918B	18

Front Axle

Capacity	Steering Gear	
12000		<input checked="" type="checkbox"/> Power <input type="checkbox"/> Manual

Rear Axle

Make	Model	Axle Ratio	
EATON	DSH40	3:90	<input type="checkbox"/> Single <input checked="" type="checkbox"/> Tandem <input type="checkbox"/> Tri Axle

Rear Suspension

Make	Type	Capacity
AIR TRAK	AIR	40000

Brakes

<input type="checkbox"/> Hydraulic	<input checked="" type="checkbox"/> Air	<input type="checkbox"/> Vacuum Assist
------------------------------------	---	--

Fuel Tanks

No.	Capacity	Material	Finish
2		<input checked="" type="checkbox"/> Aluminum <input type="checkbox"/> Steel	<input checked="" type="checkbox"/> Polished <input type="checkbox"/> Painted <input type="checkbox"/> Step <input type="checkbox"/> Saddle

Fifth Wheel

Make	Type	Operation
FONTAINE	<input type="checkbox"/> Fixed	<input checked="" type="checkbox"/> Slider <input type="checkbox"/> Manual <input checked="" type="checkbox"/> Air

Front Wheels

<input checked="" type="checkbox"/> Aluminum	<input type="checkbox"/> Steel
<input checked="" type="checkbox"/> Polished	<input type="checkbox"/> Chrome <input type="checkbox"/> Painted

Rear Wheels

<input checked="" type="checkbox"/> Aluminum	<input type="checkbox"/> Steel
<input checked="" type="checkbox"/> Polished	<input type="checkbox"/> Chrome <input type="checkbox"/> Painted

Front Tires

Size	Make	Type	
24.5 ALUM		<input type="checkbox"/> Recaps <input checked="" type="checkbox"/> Radials	LRFO 95 % LRRO 95 % LRFI 95 % LRRR 95 %
LF	90		

Rear Tires

Size	Make	Type	
24.5 ALUM		<input type="checkbox"/> Recaps <input checked="" type="checkbox"/> Radials	RRFO 95 % RRRO 95 % RRFI 95 % RRRR 95 %
RF	90		

Cab

<input type="checkbox"/> COE <input checked="" type="checkbox"/> Conv. <input type="checkbox"/> Sleeper	Sleeper Size/Type NONE
---	---------------------------

Equipment

<input type="checkbox"/> Wet Kit <input checked="" type="checkbox"/> A/C	<input type="checkbox"/> Winter/Operator Pts <input type="checkbox"/> Heated Mirror
---	--

Exterior

#Colors 2	<input type="checkbox"/> Special Paint <input type="checkbox"/> Custom Pin Stripe <input type="checkbox"/> Murals
--------------	---

Frame

<input type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Steel	<input type="checkbox"/> Heat Treated <input type="checkbox"/> Std. Length <input type="checkbox"/> Extended <input type="checkbox"/> Reinforced
--	---

Prior Damage

--

Notes

PAINTED TANKS AND AIR CLEANERS HEATED LIGHTED MIRRORS DROP SUN VISOR STAINLESS DUAL EXHAUST 2 TONE CAB AND HOOD REAR OF CAB CHROME LOAD LAMPS 4 AIR HORNS
--

Estimated Parts Total

\$0.00

Inspected by

_____ Date	_____ Signature
----------------------	---------------------------