

BBS TRUCK PAINT AND BODY

2425 TRI-STATE RD
 TEXARKANA, TX, 75501
 Tel: 903-831-5049 Fax: 903-832-3729
 BBSTRUCK@YAHOO.COM
 Tax ID: 75-2816216

Vehicle Inspection**Inspected by:****Appraised for:**

Accident Date:

Date of Loss:

Date: 2/8/2013

Estimate#:

Arrival Date:

Policy Number:

Type of Loss:

Claim Number:

Year 2007	Make VOLVO	Model VNL/VNM	Color White	Trim	License	Serial#/VIN# 4V4NC9TJ87N4790 50
Wheelbase		Unit Number	Hubometer	Engine Hours	Odometer	

Engine

Make Cummins	Model ISX	Horsepower 475	Pur.Date/Amount	<input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel
------------------------	---------------------	--------------------------	------------------------	--

Transmission

Make Fuller	Model FRO16210C	Speeds 10
-----------------------	---------------------------	---------------------

Front Axle

Capacity	Steering Gear Ross TRW	<input checked="" type="checkbox"/> Power <input type="checkbox"/> Manual
-----------------	----------------------------------	--

Rear Axle

Make Meritor	Model FOR002911 59	Axle Ratio 3.36	<input type="checkbox"/> Single <input checked="" type="checkbox"/> Tandem <input type="checkbox"/> Tri Axle
------------------------	---------------------------------	---------------------------	--

Rear Suspension

Make Volvo	Type Air	Capacity
----------------------	--------------------	-----------------

Brakes

<input type="checkbox"/> Hydraulic	<input checked="" type="checkbox"/> Air	<input type="checkbox"/> Vacuum Assist
------------------------------------	---	--

Fuel Tanks

No. 2	Capacity 150	<input checked="" type="checkbox"/> Aluminum <input type="checkbox"/> Steel	<input checked="" type="checkbox"/> Polished <input type="checkbox"/> Painted <input type="checkbox"/> Step <input type="checkbox"/> Saddle
-----------------	------------------------	--	--

Fifth Wheel

Make Fontaine	<input type="checkbox"/> Fixed	<input checked="" type="checkbox"/> Slider <input type="checkbox"/> Manual <input checked="" type="checkbox"/> Air
-------------------------	--------------------------------	--

Front Wheels

<input checked="" type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Polished	<input checked="" type="checkbox"/> Steel <input type="checkbox"/> Chrome <input checked="" type="checkbox"/> Painted
--	---

Rear Wheels

<input checked="" type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Polished	<input checked="" type="checkbox"/> Steel <input type="checkbox"/> Chrome <input checked="" type="checkbox"/> Painted
--	---

Front Tires

Size	22.5	<input type="checkbox"/> Recaps <input type="checkbox"/> Radials	LRFO	Aluminum	%
Make			LRRO	Aluminum	%
LF			LRFI	Steel	%
			LRRR	Steel	%

Rear Tires

Size	22.5	<input type="checkbox"/> Recaps <input type="checkbox"/> Radials	RRFO	Aluminum	%
Make			RRRO	Aluminum	%
RF			RRFI	Steel	%
			RRRI	Steel	%

Cab

<input type="checkbox"/> COE <input type="checkbox"/> Conv. <input checked="" type="checkbox"/> Sleeper	Sleeper Size/Type
---	-------------------

Equipment

<input type="checkbox"/> Wet Kit <input checked="" type="checkbox"/> A/C	<input type="checkbox"/> Winter/Operator Pts <input type="checkbox"/> Heated Mirror
---	--

Exterior

#Colors White	<input type="checkbox"/> Special Paint <input checked="" type="checkbox"/> Custom Pin Stripe <input type="checkbox"/> Murals
------------------	--

Frame

<input type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Steel	<input type="checkbox"/> Heat Treated <input checked="" type="checkbox"/> Std. Length <input type="checkbox"/> Extended <input type="checkbox"/> Reinforced
--	--

Prior Damage

--

Notes

--

Estimated Parts Total

	\$0.00
--	--------

Inspected by

Date	Signature